



State of Utah
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

Michael O. Leavitt
Governor

Kathleen Clarke
Executive Director

Lowell P. Braxton
Division Director

1594 West North Temple, Suite 1210
PO Box 145801
Salt Lake City, Utah 84114-5801
801-538-5340
801-359-3940 (Fax)
801-538-7223 (TDD)

September 25, 2001

TO: Minerals File

FROM: Paul Baker, Reclamation Biologist *PAB*

RE: Site Inspection, Quality Building Stone, Inc., Red Cloud Quarry, S/015/083, Emery County, Utah

Date of Inspection: September 18, 2001
Time of Inspection: 1:45-2:25 p.m.
Participants: Paul Baker, DOGM
Conditions: Mostly clear, 80's

Purpose of the inspection:

There was no specific purpose for the inspection. I was in the area and decided to visit the site.

Getting to the site:

Beginning at SR 10 about 1.5 miles south of the intersection with SR 29 which leads to Orangeville, turn east on a well-maintained county road which crosses the San Rafael Swell to US Highway 6 near Woodside. The turnoff to the quarry is, according to my odometer, 10.9 miles from SR10. At 10.7 miles, there is a fence with a cattle guard. Proceed 0.2 miles beyond the fence to a two-track road that leads south. Follow this road past the two small knolls on the west. Dropping below the rim, there is a sort of amphitheater extending to the west and south. According to the map submitted with the NOI, the quarry will be on the west side of this amphitheater.

Observations:

Tony Gallegos visited the site in January 2000 and took several photographs. I was able to find the areas photographed to confirm the site location. I saw no sign of quarrying activity although there is some disturbance in the area, probably from campers.

Conclusions and Recommendations:

No follow-up is necessary.

jb

cc: Wes Hansen, Quality Building Stone
Will Stokes, SITLA
S15-83ine.doc